

CHAL 080
Copy 5 of 5

25X1A

2 December 1959

MEMORANDUM FOR: Chief, Materiel Branch, DPD

SUBJECT: Camera Heater/Blowers

1. The Air Force unit at Del Rio recently experienced a malfunction of the camera heater/blower system on the U-2 which could have caused serious equipment damage. In the Del Rio incident, the blower system failed, but the heater continued to operate. This concentrated heat, without deflection or dissipation from the blowers, caused blistering of paint on cameras installed at the time. There would also be the increased possibility of a fire in the equipment bay if the heaters continued to operate for a prolonged period.

2. It has been determined that we gain an increase in photographic quality if the heater/blower system is left on during a photo mission. This tends to stabilize temperature within the equipment bay and reduce expansion and contraction of camera parts.

3. In order to eliminate the possibility of camera heaters being operated if a blower failure is experienced, recommend that a 'fail-safe' feature be incorporated in the wiring circuit which would stop the heaters if blower system fails, or vice versa.

STANLEY W. BEERLI
Colonel USAF
Chief, Operations Branch, DPD

RSQ:bm
1&2 - Addressee
3 - Ops subj
4 - Ops chron
5 - CHAL chron

25X1A

Approved For Release 2002/07/31 : CIA-RDP63-00313A000600040062-4

SECRET

CHAL 0003
Copy 6 of 6

2 December 1959

MEMORANDUM FOR: Acting Chief, DPD

THROUGH: Chief, Materiel Branch, DPD

SUBJECT: U-2 Handbook Revision

25X1A

1. During a visit to Headquarters by [redacted] Hycon, on 2 December 1959, that portion of the current U-2 Handbook which deals with camera configurations and procedures was discussed. This portion of the handbook is in need of revision, and [redacted] was requested to review subject data with a view of incorporating the latest data at the next handbook revision meeting.

25X1A

25X1A

2. [redacted] was requested to coordinate attendance of a Hycon representative at the next handbook revision meeting with

25X1A
25X1A

[redacted] at [redacted]

[redacted]

STANLEY W. BEERLI
Colonel USAF
Chief, Operations Branch, DPD

NOTED:

25X1A

12/2/59 SIGNED

[redacted]
Chief, Materiel Branch, DPD

RSQ

- 1&2 - Addes
- 3 - Mat/DPD
- 4 - Ops subj
- 5 - Ops chron
- 6 - CHAL chron

This document contains information
relating to the U-2 program
which is classified as SECRET

Approved For Release 2002/07/31 : CIA-RDP63-00313A000600040062-4

SECRET

127